


ABSTRACTA

My Hive Workstation

Monteringsanvisning/ Assembly Instructions ver 1.1


Including components:

1




Screw (4x)

2




Shaft (6x)

3




Plastic foldable corner (2x)

4




Screw (10x)

5



Screw (4x)

6



Screw (13x)


Notes!

1. For electrical installation use only authorized electricians.

2. When using the adjustable table for the first time: Hold down the two buttons on the remote controll until a signal sounds.


3. Maximum weight on table 100 kg

8




Alu profile middle (1x)

7



Alu profile Left (1x)

9



Alu profile right (1x)

10






Table Top (1x)

11




Control box (1x)

12



Remote control (1x)


13



Strut (1x)


Note! - Included cables only for control box to outlet. Control box to mechanism and Remote to control box.

14




Felt Hood (1x)

15




Left Screen (1x)

16



Right Screen (1x)

17






Middle Screen (1x)

ABSTRACTA

My Hive Workstation

Monteringsanvisning/ Assembly Instructions ver 1.1




Step 1
Place pos. 3 on pos. 6, 7
and pos. 8 before
step 3

Step 2
Before step 3 make sure that
frame are placed flat horizontally on floor

See Screen connectors guide when
assembling multiple units

Use the pre assembled feet
to set the frame horizontally








Step 3
Make sure you have placed electrical cables
in aluminum profiles before mounting the Screens.

ABSTRACTA

My Hive Workstation

Monteringsanvisning/ Assembly Instructions ver 1.1



ABSTRACTA

My Hive Workstation

Monteringsanvisning/ Assembly Instructions ver 1.1

